**VARISTOR (VDR) AND ARRESTOR ADD-ON – VERY LOW CURRENT SOURCE**
For testing at high voltage and very low current / low dissipation power

Adjustable between 10 uA and 2 mA, use 2 mA with care
Usable to at least 1000 V input

1	5 – 15 uA, most internal leakage
2	15 – 25 uA
3	50 uA
4	100 uA / 0.1 mA
5	0.2 mA
6	0.5 mA
7	1 mA
8	2 mA

Set open voltage to 50 – 200 V above VDR specs

PE1ABR