



PNP = BC560
NPN = BC550

GAINF-UK.SCH

Due to the potentiometer and switch wiring oscillation feedback on high freq. occurred between in- and output. It could be suppressed by the 1 MHz low-pass filter.

4th version amplifier/buffer module
Update V2 for the 3rd version !

| | | |
|---------------------------------|-----------------|----------|
| Title | | |
| 455 kHz FILTER BUFFER AMPLIFIER | | |
| Size | Document Number | REV |
| A | made by PE1ABR | 3.2 |
| Date: | May 18, 2012 | Sheet of |