



- See separate TXT files with improvements for:
- A) the TL497 part of the diagram.
 - B) A13 timing solution
 - C) General timing requirements
 - D) Other improvements for Vpp - Vcc switch

Title		
SUNSHINE EW904B EPROM PROGRAMMER		
Size	Document Number	REV
B	REVERSE ENGINEERED BY W. GEERAERT	
Date: September 7, 1999	Sheet	3 of 4